



AppleTalk

#7: MLIACTV Flag and the Iie Workstation Card

Written by: Mark Day & Dan Strnad

November 1989

This Technical Note describes a problem using the MLIACTV flag with the Iie Workstation Card.

When using the Apple Iie Workstation Card, the MLIACTV flag does not always show that the MLI (or PFI) is active. This inconsistency can cause programs that use the MLIACTV flag to fail when making MLI calls from interrupt routines. Programs can correct for this problem by making all MLI calls through the NewMLI routine listed in this Note and checking the NewMLIActv flag instead of the MLIACTV flag. This approach solves the problem only if **all** MLI calls, including those made by any interrupt routines, are made through this routine.

The following routine is a replacement for the MLI entry point at \$BF00. Programs using this routine can perform a JSR to NewMLI instead, which fixes the problem. Section 6.2.1 of the *ProDOS 8 Technical Reference Manual* details how programs can cause the MLI to return the their routine rather than the routine that originally called it. For programs using this technique that are also using the routine below, the location below labeled NewCmdAddr replaces CmdAddr (\$BF9C). The steps involved in patching the MLI return location still apply, as specified in Section 6.2.1 of the ProDOS 8 Technical Reference.

```
; MLI patch for Apple II Workstation Card
; by Mark Day
;
; code shown is compatible with MPW IIGS cross-assembler
;
; Your program should use the NewMLIActv flag instead of
; MLIACTV ($BF9B), and should JSR NewMLI instead of
; JSR MLI ($BF00).
;
machine      M6502          ; 6502 code for //e
longa off
longi off

parmptr     equ    0          ; two bytes on zero page
MLI         equ    $BF00     ; entry to the real MLI

NewMLI proc

    php                      ; save old interrupt status to
    pla                      ; temporarily disable interrupts
    sta oldp                 ; so that NewCmdAddr is always valid
    sei                      ; when an interrupting routine sees
                            ; NewMLI active.
```

```
sec  
ror   NewMLIActv   ; NewMLI is now active!
```

```

;
; We need to get the return address from the stack so we can
; get the command number and parameter block address which
; follow the JSR NewMLI, and so we can save NewCmdAddr.
;
        clc
        pla                ; get low byte of parm address - 1
        sta    parmptr
        adc    #4          ; get real return address
        sta    NewCmdAddr
        pla
        sta    parmptr+1  ; save high byte of parm address - 1
        adc    #0
        sta    NewCmdAddr+1 ; save real return address

        lda    oldp
        pha
        plp                ; reinstate old interrupt status
;
; Now, we copy the call number and parameter list pointer that followed
; the JSR NewMLI, and copy them after a JSR to the real MLI.
;
        tya                ; save Y on stack
        pha
        ldy    #1          ; offset to command number
        lda    (parmptr),y ; get command number
        sta    NewCmdNum
        iny
        lda    (parmptr),y ; point to parm list ptr (low)
        sta    NewParmPtr
        iny
        lda    (parmptr),y
        sta    NewParmPtr+1
        pla                ; unstack value of y register
        tay

;
; Now, call the real MLI with the user's command and parameter list
; and jump back to our caller.
;
        jsr    MLI        ; call the real MLI
NewCmdNum    dc.b    0    ; command number
NewParmPtr   dc.w    0    ; parameter list pointer

        php                ; save C because LSR changes it!
        lsr    NewMLIActv ; MLI is no longer active
        plp                ; restore C
        dc.b    $4C        ; JMP absolute instruction
NewCmdAddr   dc.w    0    ; target of jump, caller's return address

NewMLIActv   dc.b    0    ; $80 bit set if MLI active
oldp         ds.b    1    ; used to preserve processor status

        endp
        end

```

Note that this routine also works on the Apple IIGS, even though the problem with the MLIACTV flag only affects Apple IIe Workstation Cards.

Further Reference

- *AppleShare Programmer's Guide for the Apple IIGS*
- *ProDOS 8 Technical Reference Manual*